

## Magnet Welding Angles MSA | MS2 | MAV | PA

## Switchable permanent magnets

Your universal magnet clamp for small welding and assembly works. All magnetic angles are switchable and suitable for flat and round material, except SW.

MAV 120 and PA 200 are stepless adjustable angles.











MAV 120

PA 200

## **Features**

- Easy positioning, adjusting and fixing of worknieces
- No disflection or influence of welding arc
- The contact areas of MS, MAV 120 and PA 200 are separately switchable
- The angle of MAV120 and PA200 is quickly set by scale







Technical data	Dimensions [L×WxH]	Angle	Switchable	Use also for Round material	Adhesive force		No.
	[mm]				[kg]	[kg]	
MSA I	110 x 30 x 95	45°/90°	Ja	Ja	36	0,7	45338
MSA II	150 x 35 x 130	45°/90°	Ja	Ja	60	1,4	45339
PA 200	240 x 41 x 240	22°-270°	Ja *	Ja	90	1,6	60343
MS2-80	153 x 38 x 153	90°	Ja *	Ja	46	1,2	48192
MS2-90	195 x 46 x 195	90°	Ja *	Ja	68	2,7	18736
MS2-300	330 x 330 x 32	90°	Ja	Ja	3x 120	4,0	70505
MS2-450	550 x 550 x 45	90°	Ja	Ja	3 x 300	4,0	70507
MAV 120	197 x 50 x 197	30°-275°	Ja *	Ja	41	2,4	162

<sup>\*</sup> Every thigh is separately switchable